

06-26-03 Construction Site Visit



MI-65 Target Service Building looking North east

3819



Installation of pipes in Target Shaft

3826



Utility Room piping

3828



Target Hall with steel hand rails in place

3829



Pre-Target Hall

3832



Increasing the width of the of door\way in pre-target

3833



Shotcreted angle irons in the Target Hall walkway

3834



Absorber Access Tunnel

3837



Installation of piping in MINOS shaft

3839



Shotcreting of MINOS Hall Walkway

3842



Hose end of shotcrete equipment

3840



Hopper for shotcrete

3841



MINOS Hall

3843



3844



MINOS Hall looking north east

3849



MINOS Hall looking south west

3846



Near Detector racks

3855



Near Detector planes with mock-up of walkway on the right

3857



Installation of equipment in racks

3858



3858